



	Service Letter SL 1	EB - Nr. I - EC 34
--	--------------------------------	-----------------------

Planning Information

Affected Parts:

Lag screws Part no. A-983-85 (hexagon head) and lag screws Part no. A-983-65 (hexagon head)

Affected Propellers:

All Constant Speed Propellers.

Reason:

Replacing of lag screws Part No. A-550-85 since Dec. 12. 1998 and lag screws Part No. A-550-65 since April 1999.

The new lag screws (A-983-()) are designed to withstand higher dynamically loads and stresses.

Description:

Components introduced by this Service Letter are incorporated into the MT-Propeller Manuals E-220, E-250, E-310, E-373, E-519, E-520, E-571, latest Issues.

Affected Publications:

Overhaul Manual E-220, Hydraulically Controlled Variable Pitch Propeller MTV-5-(), -6-(), -9-(), -11-()
-12-(), -14-(), -15-(), -16-(), -21-(), -22-(), -25-()

Overhaul Manual E-250, Electrically Controlled Variable Pitch Propeller MTV-1-(), -7-(), -10-(), -17-(),
-18-(), -20-()

Overhaul Manual E-310, Mechanische Verstellpropeller MTV-24-()

Overhaul Manual E-373, Hydraulic Constant Speed Propeller MTV-2-(), MTV-3-()

Overhaul Manual E-519, Reversible Hydraulically Controlled Variable Pitch Propeller MTV-5-1-, -9-,
-12-, -14-, -16-1-, -25-2-, -27-1-()-R(M)

Overhaul Manual E-520, Reversible Hydraulically Variable Pitch Propeller MTV-25-1-()-R(M)

Overhaul Manual E-571, Hydraulically Controlled Variable Pitch Propeller

Material Information

Lag Screws Part No. **A-983-65** (Hexagonhead) replace lag screw Part No. A-550-65.

Lag Screws Part No. **A-983-85** (Hexagonhead) replace lag screw Part No. A-550-85.

This modification was incorporated in all inspection check of records.

Freigabe MPL Clearence MPL Datum: May 12,1999 Date	Ausgabe Edition vom: May 12,1999 Date		Blatt Nr. 1 Page No. von 1 of
---	--	--	--