



	Service Letter SL 14 D	EB - Nr. JAA-LBA.NJA.009
--	---	-----------------------------

Important Information

New blade seals in constant speed MT-propellers

Affected Procedure:

Installation of new blade seals.

Affected Propellers:

All MTV Constant Speed Propellers.

Reason:

From March 20, 2003 the blade seals are replaced by special surface treated ring-seals C-057-() to avoid grease leakage.

Required Material:

Since March 20, 2003 the improved ring seal is available for:
Seal Part No. C-057-92
Seal Part No. C-057-78
Seal Part No. C-057-64

Additional Information:

In case that other blade seals will be installed, no warranty claim for grease leakage on the blade roots will be accepted by MT-Propeller.

Publications affected:

Manuals will be updated as soon as the new blade seals will be standard in production and overhaul.

<i>Clearance MPL</i>	<i>Edition</i>		<i>Page No. 1</i>
			<i>Of 1</i>
<i>Date March 20, 2003</i>	<i>Date March 20, 2003</i>		