



	Service Letter SL 19	EB - Nr. JAA-LBA.NJA.009
--	---------------------------------	-----------------------------

Planning Information

Affected Parts:

Control Unit P-120-A (Serial Numbers until 01-XXX and from WA01-XXX)

Affected Propellers:

All airplanes and motor gliders with an electrical variable pitch MT-propellers with a Control Unit P-120-A

Reason:

The outside housing dimension from P-120-A with serial no. WA01-XXX has been changed. The length of the new Control Unit housing is increased by 20 mm (0,78").

Affected Publications:

Operation and Installation Manual List E-118

Remark:

If a new Control Unit with the serial number WA 01-XXX is ordered for a new installation or exchange of the older Control Unit P-120-A, it must be taken into account that there is still enough space for the installation in the cockpit panel.

Freigabe MPL Clearence MPL Datum: October 24, 2001 Date	Ausgabe Edition vom: Oct. 24, 2001 Date		Blatt Nr. 1 Page No. von 1 of
--	--	--	--