



	Service Letter SL 20A	DOA - No. EASA.21J.020
--	----------------------------------	---------------------------

Planning Information

Affected Parts:

Replacement of MTV-9/ -12 / -14/ -16 front plate.

Only applicable if old hub is manufactured before 2001 and is replaced with new propeller hub manufactured after the year 2001.

Affected Propellers:

Replacement of the front plate at MTV-9/ -12 / -14/ -16, standard, with feather and with reverse (M), (P).

Reason:

The front plate dimensions has been changed.

Description:

Since March 2001 the front plates for the MTV-9-(), MTV-12-() and the MTV-14-() are installed with the new hub and since November 2001 for the MTV-16-() is installed with the new hub, as described in the Overhaul Manual E-220 (ATA 61-12-20).

Affected Publications:

Operation and Installation Manual List E-220, E-519, E-680

Material Information

	<u>Old Part No.</u>	<u>New Part No.</u>
MTV-9-()	A-445-A or A-916-B	A-1245-()
MTV-9-()-C-F	A-843-A	A-1244
MTV-9-()-C-F-R(M)	A-989-A-()	A-1246-()
MTV-12-()	A-445-A or A-916-B	A-1245-()
MTV-12-()-C-F	A-843-A	A-1244
MTV-12-()-C-F-R(M)	A-989-A-()	A-1246-()
MTV-14-()	A-445-A or A-916-B	A-1245-()
MTV-14-()-C-F	A-976-A	A-1248
MTV-14-()-C-F-R(M)	A-1035-A-R	A-1272-R/-L
MTV-16-()	A-918-A or A-451	A-1284
MTV-16-()-C-F	A-936-A	A-1283
MTV-16-()-C-F-R(M)	A-1028-B	A-1286-L
MTV-16-()-C-F-R(P)	A-1177	A-1177-A

<u>Clearance MPL</u>	<u>Edition</u>		
Martin Albrecht	Fini Hoell		
Date: February 19, 2009	Date: February 19, 2009		
		Page	1 of 1