



	Service Letter SL 3	EB - Nr. I - EC 34
--	--------------------------------	-----------------------

Planning Information

Affected Parts:

All blades of variable pitch propellers.

Affected Propellers:

All Constant Speed Propellers.

Reason:

Modification of the pitch change pin location to decrease the necessary servo pressure or current (electrically variable pitch propeller) to actuate the propeller blades.
This modification was introduced since Jan. 1997 in general and since May 1997 for MTV-12 and MTV-14.

Description:

Components introduced by this Service Letter are incorporated into MT-Propellers Service Instruction E-581

Freigabe MPL <i>Clearence MPL</i> Datum: May 12, 1999 <i>Date</i>	Ausgabe <i>Edition</i> vom: May 12, 1999 <i>Date</i>		Blatt Nr. 1 <i>Page No.</i> von 1 <i>of</i>
--	---	--	--