

	Service Letter SL No. 46	DOA No. EASA.21J.020
--	-------------------------------------	---------------------------------

IMPORTANT INFORMATION

Affected Parts: Fittings installed on Unfeathering Accumulator P-893-()/P-905-()

Affected Aircrafts: All Diamond DA 42 with Thielert/Austro/Lycoming engine

Description: The following Fittings C-181-1 (0°), C-167 (45°), C-168 (90°) are installed on the Unfeathering Accumulator P-893-()/P-905-() which are manufactured **before** March 2009 (Part No. accessory Cover A-1439-A)



The following Fittings C-179 (0°), C-177 (45°), C-178 (90°) are installed on the Unfeathering Accumulator P-893-()/P-905-() which are manufactured **after** March 2009 (Part No. accessory Cover A-1439-B)



Contact: MT-Propeller Entwicklung GmbH
Flugplatzstrasse 1
94348 Atting
Germany
e-mail: techsupport@mt-propeller.com

<i>Check/Approved by: MPL</i>  Martin Albrecht Date: September 28, 2012	<i>Issued by:</i>  Andreas Seperant Date: September 28, 2012		Page No 1 of 1
--	---	--	----------------