

	Service Letter SL No. 47	DOA No. EASA.21J.020
--	-------------------------------------	---------------------------------

IMPORTANT INFORMATION

Affected Parts: Blade seal installation during propeller assembly


Affected Propeller: All MTV Propellers

Description: During blade seal installation on the blade ferrule, it is possible to install the blade seal twisted. In case the blade seal is installed as shown in Fig.3, a possible grease leak will occur during operation.

To avoid the grease leak, check for correct blade seal installation as shown in Fig.2.




Fig.1



Correct installed

Fig.2




Wrong installed

Fig.3

Affected Publications: Overhaul Manual E-220, E-519, E-520, E-571, E-680

Contact: MT-Propeller Entwicklung GmbH
Flugplatzstrasse 1
94348 Atting
Germany
e-mail: techsupport@mt-propeller.com

Check/Approved by MPL  Martin Albrecht Date: January 14, 2013	Issued by:  Andreas Seperant Date: January 14, 2013		Page No 1 of 1
---	---	--	----------------