



	Service Letter SL 54	DO - No. EASA.21J.020
--	---------------------------------	----------------------------------

Planning Information:

Replacement of parts during overhaul or repair as listed below.

Affected Propeller:

MTV-27-1-N-C-F-R(G)-J with blade type CFR285-82 or CFRL285-82 for Jetstream 41

Affected Parts:**Piston Extention :**

A-1747-71,5 is replaced by A-1747-A-71,5

Pitch Change Fork:

A-1739-()-R/L is replaced by A-1739-C-R/L

Guide Block:

A-1644-1-() is replaced by A-1644-1-B

Reason:


Technical Improvement

Affected Publications:

Overhaul Manual E-680

Contact:

MT-Propeller Entwicklung GmbH
Flugplatzstrasse 1
94348 Atting
Germany
e-mail: techsupport@mt-propeller.com

Check/Approved by  Martin Albrecht Date: Jul 25, 2013	Issued by:  Andreas Seperant Date: Jul 25, 2013		Page No 1 of 1
--	--	--	----------------