



	Service Letter SL 59	DO - No. EASA.21J.020
--	---------------------------------------	--

Planning Information

Affected Parts:

Counterweight body crack inspection(Magnetic particle inspection)

Affected Propellers:

All counterweighted variable pitch MT Propeller

Reason:

During the magnetic particle inspection some material manufacturing characteristics (see Marks on Fig 1, Fig 2, Fig 3) were found.

Such indications do not affect the strength of the counterweight.


Affected Publications:

Overhaul Manual E-220, E-250, E-519, E-680

Required Action:



No action required, such counterweight bodies can go in service again.

Fig.1



Check/Approved by: <i>[Signature]</i> Martin Albrecht Date: Feb 19, 2015	Issued by: <i>[Signature]</i> Andreas Seperant Date: Feb 19, 2015	Page No 1 of 2
--	---	----------------

	Service Letter SL 59	DO - No. EASA.21J.020
--	---------------------------------	----------------------------------

Fig.2**Fig.3****Contact:**

MT-Propeller Entwicklung GmbH
Flugplatzstrasse 1
94348 Atting
Germany
e-mail: techsupport@mt-propeller.com