

	Service Letter SL 64	DO - No. EASA.21J.020
--	---------------------------------	----------------------------------

Alternative Positioning of MT-Propeller Identification Label**Affected Propeller:**

All MTV-Propeller which have no identification label on the propeller blade

Description:

If the propeller blade has no identification label stuck on, an alternative positioning of the MT-Propeller identification label (part number A-950-3) is optional possible as shown on the picture below.

**Contact:**

e-mail: techsupport@mt-propeller.com

Clearence MPL

Frank Grum

Date: February 02, 2017

Edition

Andreas Seperant

Date: February 02, 2017

This technical Information has been approved according the procedures established for the EASA-certified Design Organization No.: EASA.21J.02