



	Service Letter SL 21B	EB - Nr. JAA-LBA.NJA.009
--	----------------------------------	-----------------------------

Planning Information

Effected parts:

Replacing of Aeroshell 5 by MT 2 Propeller Grease.

Reason:

In the past grease leakage occurred under certain conditions.
 As a corrective action Aeroshell 5 is replaced by MT 2 Propeller Grease, which has a higher viscosity.

Description:

Since 1st July 2002 Aeroshell 5 is replaced by MT 2 Propeller Grease for new propeller as well as during overhaul and repair.

On 2nd October 2002 MT 2 Propeller Grease has additionally improved viscosity behavior.

Publications Affected:

Manuals will be updated as soon as the new grease will be standard in production and overhaul.

Material Information

MT 2 Propeller Grease is a long-term grease with MT additive combination.

MT 2 Propeller Grease can be ordered at
 MT-Propeller Entwicklung GmbH
 Flugplatz Str. 1
 94348 Atting
 Germany

<i>Clearence MPL</i>	<i>Edition</i>		<i>Page No.1</i>
<i>Date: 04.11.2002</i>	<i>Date: 04.11.2002</i>		<i>of 1</i>