



	Service Letter SL 73 R1	DO - No. EASA.21J.020
--	------------------------------------	--------------------------

Optional installation of the blade bearing A-1540

Affected Propeller:

MTV-27-1-E-C-F-R(G)/CFRL240-55d installed on Mitsubishi MU-2B series

and

MTV-27-1-E-C-F-R(G)/CFRL250-103 installed on M7 AEROSPACE LP (Former FAIRCHILD AIRCRAFT) SA227 series or Metro series.

Affected Publication:

Overhaul Manual E-680

Description:

instead of the standard blade bearing A-233- () the optional blade bearing A-1540 (Cronidex Material) can be installed into the MTV-27-1-E-C-F-R(G) / CFRL240-55d and MTV-27-1-E-C-F-R(G)/CFRL250-103 Propellers) to improve the long-time wear.

Contact: e-mail: techsupport@mt-propeller.com

Edition:  Andreas Seperant	Original Issue: July 24, 2020 Revision 1: March 20, 2023	Clearance MPL:  Martin Albrecht
--	---	---