



DO - No. EASA.21J.020	Service Letter SL 83	Revision 1
--------------------------	---------------------------------	------------

Alternative approved paint for paint corrections on propeller blades and domes

Type Affected: All propeller models used on Cirrus aircrafts

For local repairs such as minor scratches, alternative paints may be used to paint the blade tips if the paint listed within SI-68 is not available or preferred.

Alternative Sherwin Williams Paint include (any color):

- Sherwin Williams Polane T Polyurethane Enamel
(2 Component)
- Sherwin Williams 855 Series SKYscapes
General Aviation Basecoat Colors
(Basecoat-clearcoat process)
- Sherwin Williams 858 Series SKYscapes
Single Stage System

The paint manufacturer's application instructions must be followed.


Additional information for painting the spinner dome:

Any paint from any manufacturer can be used to match the cowling and airframe color.

For the spinner dome no restrictions for painting is applicable.

Further Information: Service Instruction No. 68

Contact: MT-Propeller Entwicklung GmbH
Flugplatzstr. 1
94348 Atting
Germany
e-mail: techsupport@mt-propeller.com

Prepared by:  Lara Neitzel	Original Issue: August 26 th , 2025 Revision 1: October 30 th , 2025	Checked / Approved: Office of Airworthiness  Martin Albrecht
---	---	--